1. Approving Competent Authority/Country	2.	3. Form Tracking Number
Civil Aviation Authority/Czech Republic	**AUTHORISED RELEASE CERTIFICATE** **EASA FORM 1**	**159380-1**

4. Organisation Name and Address	5. Work Order/Contract/Invoice
JOB AIR Technic a.s. **Gen. Fajtla 370** **742 51 Mošnov**	**W9826**

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	FLAP ACTUATOR NO.3	793C0000-01	1,00	X20444	INSPECTED/TESTED

12. Remarks

RH FLAP ACTUATOR NO.3 HAS BEEN REMOVED IN SERVICEABLE CONDITION FROM A/C A320, MSN 1657, REG.: OE-IOP I.A.W. AMM 27-54-49-000-003-A, REV. 31, MAY 01/2022

FLAP ACTUATOR:
TSN: 52 181:30 FH
CSN: 23 173 FC

AIRFRAME:
TAH: 52 181:30 FH
TAC: 23 173 FC

13a. Certifies that the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145 and in respect to that work, the items are considered ready for release to service.

13b. Authorised Signature	13c. Approval /Authorization No.	14b. Authorized Signature	14c. Certificate/Approval Ref. No.
		PL 449	**CZ.145.0054**
13d. Name (Typed or Printed)	**13e. Date (dd/mmm/yyyy)**	**14d. Name (Typed or Printed)**	**14e. Date (dd/mmm/yyyy)**
		Mateusz Ojciec	**01 Jul 2022**

User/Installer Responsibilities

1. This certificate does not automatically constitute authority to install the item(s).

2. Where the user/installer performs work in accordance with the regulations of an airworthiness authority different than the airworthiness authority specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority of the country specified in Block 1.

Powered by CamScanner

job air technic

Work Order: W9826

PN: 793C0000-01 | Descr: FLAP ACTUATOR NO.3 | Qty: 1

S/N: X20444

Customer: JOB AIR Technic a.s. | Ref No.: IO12739

Task No.: 1

Start:

1004981S

Work Required			
PLEASE REMOVE FLAP ACTUATOR IN SERVICEABLE CONDITION			
Final Action		Date	Performed by
RH FLAP ACTUATOR NO.3 HAS BEEN REMOVED IN SERVICEABLE CONDITION FROM A/C A320, MSN 1657, REG.: OE-IOP I.A.W. AMM 27-54-49-000-003-A, REV. 31, MAY 01/2022		01-07-2022	JAT 449
Certification			
First Insp. Date	First Insp. Sign and Stamp	Double Insp. Date	Double Insp. Sign and Stamp
01-07-2022	JAT 449		

Powered by CamScanner